

1	P2-01	Chassis	1	A	S-43	M6x10 Screw	4	Q	N-08	3/8-16 nut	3
2	P2-2A	Transformer-220V	1	B	S-22	6-32 x 1/4" L Screw	12	R	T-08	12-10 yellow #10 stud	4
3	P2-06	Chassis Cover	1	C	S-25	8-32 x 3/8" L Screw	14	S	T-09	12-10 Yellow 1/4" stud	1
4	P2-07	Chassis Front Panel	1	D	S-31	10-24 x 1/2 MS	2	T	T-11	12-10 Ring Terminal non-insulated	1
5	P2-16-277	Circuit Breaker - 30A 277V	1	F	S-38	1/4"-20x1/2" L MS	4	U	T-12	22-16 Ring Terminal non-insulated	1
6	P2-52	1/2" hole strap	1	G	S-63	8x32x1/4" L PH phil. screw	1	V	T-16	Pin Connectors .156 kk	12
7	P-14A	Thyristor/Power Module	1	H	T-13	Ring terminal - 22-16 #10 stud	2	X	WL-14	10/3 SO CABLE CAROL	30'
8	P-20F	Intermittent Switch	1	I	S-65	3/8-16 x 1" L Hex Hd. Bolt	2	Z	WL-21	10 AWG 600V stranded black wire	5"
9	P-29	Rubber Gromet - 9/32 ID	1	K	W-08	3/8 FW	4	AA	M-12	Shoulder washer .026"ID-1/4"L	2
10	P-31	Strain Relief	3	L	W-14	3/8 LW	3	AB	ST-04	6-32 x 1/2" L plastic stand-off	4
11	P10-09	Knobs-circuit board	2	M	W-15	1/4 x 5/8 SAE FW	3	AD	T-18	Housing for Pin Connectors QUAD	2
12	P10-50	Power light (green)	1	N	W-20	1/4 LW	4	AF	WL-02	20 AWG 300V stranded wire-red	7"
13	P10-54B	Decal "Warning"	1	O	W-23	# 10 LW	2	AG	WL-03	20 AWG 300V stranded wire-black	7"
14	P10-55Y	Decal "Pro Spot"- 3/4 x 6 1/2"	2	P	W-57	#8 FW	1				
15	PR2-CB	PR-2 Circuit Board Assembly	1								

